

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.


**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

Agenda

Subject Rough Review Agenda
Project « Diaper Genie » Playtex
Date 2/8/01

- 1. Review 2D layouts of:**
 - 1.1. Latching systems
 - 1.2. Foot pedal systems

- 2. Review schematic sketches**
 - 2.1. Top opening (Pros and cons)**
 - 2.1.1. Cartridge loading option 1
 - 2.1.2. Cartridge loading option 2
 - 2.2. Side door opening (Pros and cons)**
 - 2.2.1. Cartridge loading sequence
 - 2.3. Integral bucket (Pros and cons)**
 - 2.3.1. Cartridge loading sequence
 - 2.4. Foot pedal**
 - 2.4.1. Option 1
 - 2.4.2. Option 2
 - 2.5. Motorized schematics**
 - 2.6. Cutting methods (Pros and cons)**
 - 2.6.1. Retractable cutter
 - 2.6.2. Remote cutter
 - 2.6.3. Auto-cutter, mockup and discussions.



Pros:

- More stable than side door (emptying)
- Better ergonomics
- Less squatting
- Easy disposal
- Easy reload (*anywhere you want*)
- Easy to seal (*simple cross section*)
- Cost reduction (*less part count*)

Cons


- Cartridge load might be cumbersome
- Odor control and cleaning (*no internal bucket*)
- Odor Blast
- Hygiene perception
- Limited cutter options

2.1

Top Opening

PLAYTEX Products, Inc.
Next Generation Genie - 61601
© Bresslergroup 2001

BRESSLERgroup
Philadelphia, PA USA
215.561.5100




Cartridge loading

2.2.1

PLAYTEX Products, Inc.
Next Generation Genie - 61601
© Bresslergroup 2001

BRESSLERgroup
Philadelphia, PA USA
215.561.5100



Pros:

- Easy disposal
- Easy cartridge load
- Easy access to the inside (*cleaning*)
- Any of selected cutting method is doable
- Less part count.

Cons


- Difficult to seal (*complex and extended surfaces*)
- Odor control?
- Stability?

Integral bucket

2.3

PLAYTEX Products, Inc.
Next Generation Genie - 61601
© Bresslergroup 2001

BRESSLER group
Philadelphia, PA USA
215.561.5100




2.3.1

Cartridge loading

PLAYTEX Products, Inc.
Next Generation Genie - 61601
© Bresslergroup 2001

BRESSLERgroup
Philadelphia, PA USA
215.561.5100



2.5

Motorized schematics

PLAYTEX Products, Inc.
Next Generation Genie - 61601
© Bresslergroup 2001

BRESSLERgroup
Philadelphia, PA USA
215.561.5100